

[REDACTED]

From: Brent Oldham <Brent.Oldham@bdc.govt.nz>

Date: 9 July 2024 at 2:14:45 PM NZST

To: [REDACTED]

Cc: Sarie van der Walt <Sarie.vanderWalt@bdc.govt.nz>, Wayde Dunlop
<wayde.dunlop@bdc.govt.nz>

Subject: BeforeUDig Sequence No 12768587

[REDACTED]

There are known critical BDC 3 Waters assets in and close to the area you have enquired about. Before undertaking any work at this location please liaise with Madison Jose, Three Waters Contract Manager at WestReef, phone 03 788 9090. Madison will be able to assist in identifying risk mitigation in case of a pipe strike or inadvertent damage.

BeforeUdig Sequence No 12768587 Reference Punakaiki Location: 4663 SH7 Te Miko
Shown on Map (below) in

BLUE 100mm Pressurised Water Main
LIGHT BLUE Punakaiki Water Intake

The 100mm Water Main supplies our Punakaiki Water Treatment plant and is located in the Northern road-side.

Note: Locations are approximations only, please refer to further information below the site map,



Our mapped services are available to view online at <https://gis.westcoast.govt.nz/WestMapsViewer/?map=e0f8051c6a5e483cbe7d92bb431adb98> and are updated daily

Please use this site to locate any services and note that service locations are approximate only. Appropriate service location tools will need to be utilised to determine the exact location of any pipelines in proposed areas to avoid damage. Appropriate location methods may include GPS location, pot holing, hydrovac, hand digging and use of a metal detector. Damage caused to infrastructure should be reported immediately to WestReef, phone 03 788 9090. Damages may result in BDC passing on the costs for response and repairs depending on pipe condition and location methods used. Please treat any infrastructure found, as live at all times.

Please contact **Madison Jose 3 Waters Maintenance Contract Manager at WestReef, phone 03 788 9090.**

Kind Regards,

Brent Oldham | Manager Infrastructure Planning
Mobile 027 271 9716 | Email Brent.Oldham@bdc.govt.nz

Buller District Council | Phone 0800 807 239 | www.bullerdc.govt.nz
PO Box 21 | Westport 7866

Community Driven | One Team | Future Focused | Integrity | We Care

Email Disclaimer: This correspondence is for the named person's use only. It may contain confidential or legally privileged information or both. No confidentiality or privilege is waived or lost by any mistransmission. If you receive this correspondence in error, please immediately delete it from your system and notify the sender. You must not disclose, copy or relay any part of this correspondence if you are not the intended recipient. Any views expressed in this message are those of the individual sender, except where the sender expressly, and with authority, states them to be the views of Buller District Council.



This email has been filtered by SMX. For more information visit smxemail.com



**Position of underground cables is indicative only
and must be located prior to any excavation commencing**



Electric Distribution Device

Asset group, Asset type

▲ Pole Transformer

Voltage

● 11kV

Lines/Cables

Voltage

--- UG LV

— OH 11kV

— Boundary



4663 SHWY 6
Te Miko



Scale - 1:1,000 @ A4

0 15 30 60 Metres

LINZ, West Coast RC, Esri Community Maps Contributors, LINZ, Stats NZ, Esri, TomTom, Garmin, Foursquare, METI/NASA, USGS

Q 4671 State Highway 6, Te Miko, Pu... X

AVAILABILITY

Fibre Unavailable X

Cable Unavailable X

VDSL Unavailable X

Wireless Available ✓

Farmside Variable speeds

⬇ 3-30 Mbps ⬆ 3-30 Mbps

Get wireless

[What is wireless?](#)

ADSL Available ✓

Chorus Variable speeds

⬇ 5-10 Mbps ⬆ 0.5-1.4 Mbps


Get ADSL

[What is ADSL?](#)

Availability not accurate?

[Submit feedback](#)

© Mapbox © OpenStreetMap Improve this map



LAYERS

- Fibre
- Planned fibre
- Cable
- VDSL
- Wireless
- Planned wireless
- ADSL

